Lewis Building 25-31 West Main Street Waterbury New Haven County Connecticut HABS No. CT-405

HABS CONN, 5-WATB, 10-

## **PHOTOGRAPHS**

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION, NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

Form 10-920 (June 1983)

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS CONN, 5-WATB,

## ARCHITECTURAL DATA FORM

STATE	COUNTY	COUNTY		TOWN OR VICINITY	
Connecticut	New Haven	New Haven Wat		terbury	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)				HABS NO.	
Lewis Building				CT-405	
SECONOARY OR COMMON NAMES OF STRUCTURE					
COMPLETE AOORESS (DESCRIBE LOCATION FOR RURAL SITES)					
25-31 West Main Street					
DATE OF CONSTRUCTION (INCLUDE SOURCE)  ARCHITECT(S) (INCLUDE SOUR			LUDE SOURCE)		
1903		Joseph T. Smith			
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)					
Contributing element to late nineteenth/early twentieth century commercial district.					
STYLE (IF APPROPRIATE) early Art Deco					
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)					
combination steel beam and wood joist frame, exterior walls of dressed limestone					
APE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)					
EXTERIOR FEATURES OF NOTE					
Paired windows separated by fluted pilaster strips; crenellations above each strip;					
four strips of eight continue to sidewalk level creating three storefront bays					
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)					
Steel pan stairs, terrazzo floors and treads, dark wood door trim with transom lights					
and stairwell skylights, dark wood sash and window frames					
MAJOR ALTERATIONS AND ADDITIONS WITH DATES					
MAJOR ALTERATIONS AND ADDITIONS WITH DATES 1928-1930 total remodeling interior and exterior which created present appearance					
1920 1930 cotal remodeling interior and enterior whiteh objects process approximate					
DESCRIT COMPLETION AND HOS					
PRESENT CONDITION AND USE  Good condition; thrift store first floor, upper floors vacant					
Good condition; thrift store list floor, upper floors vacant					
OTHER INFORMATION AS APPROPRIATE					
Structure to be demolished					
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)					

COMPILER, AFFILIATION Sally Cote, Assistant Executive Director,

DATE

1980